


M5b

Steel beam masonry above

Masonry hanger embedded in mortar joints. Refer to manufacturers details.



If masonry hanger is higher than the bottom flange of the Steel then a timber packer is required within the depth of the Steel